











1.1

HUS-H	$h_{nom}$	$h_1$	$t_{fix}$
10x90	85 mm	100 mm - $t_{fix}$	0 ... 5 mm
10x100	85 mm	110 mm - $t_{fix}$	0 ... 15 mm
10x120	85 mm	130 mm - $t_{fix}$	0 ... 35 mm
10x140	85 mm	150 mm - $t_{fix}$	0 ... 55 mm
10x160	85 mm	170 mm - $t_{fix}$	0 ... 75 mm
10x200	85 mm	210 mm - $t_{fix}$	0 ... 115 mm
10x240	85 mm	250 mm - $t_{fix}$	0 ... 155 mm
10x280	85 mm	290 mm - $t_{fix}$	0 ... 195 mm











2.1

			
			
$d_0$	Ø 10 mm	Ø 10 mm	Ø 8 mm



4.1

				
	SIW 14-A	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	SIW 22-A	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	SIW 22T-A	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	SI 100	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	55 Nm	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

