



HSA-F	$t_{fix,1}$ [mm]	$t_{fix,2}$ [mm]	$t_{fix,3}$ [mm]
M10 5/-/-	5	-	-
M10 20/10/-	20	10	-
M10 35/25/-	35	25	-
M10 50/40/10	50	40	10

HSA-F	1	2	3
$h_{nom}$ [mm]	50	60	90
$h_{min}$ [mm]	100	120	160
$S_{min}$ [mm]	100	100	100
$C_{min}$ [mm]	60	60	55

